

Trowel Marks on Concrete Floors

Position Statement #4

Some specifications require concrete contractors to produce floor surfaces that are free of trowel marks. However, the specifications don't define the term "trowel marks."

Both ACI 301-99, "Specifications for Structural Concrete for Buildings," and ACI 302.1R-96, "Guide for Concrete Floor and Slab Construction," use the term "trowel marks" (Section 5.3.4.2c in ACI 301 and Section 11.9 in ACI 302.1R). Neither document defines the term, nor is the meaning clear from the context in which the term is used. ACI 116R-00, "Cement and Concrete Terminology," doesn't include a definition of trowel marks.

Because differing interpretations of this term can cause problems with acceptance of the finished floor, the American Society of Concrete Contractors (ASCC) seeks to establish a consensus definition for trowel marks that is applicable during both the bidding phase and execution/acceptance of the finished floor. Establishing a common industry definition provides all parties with a fair and equitable ability to judge the acceptability of a finished floor surface.

To provide a clear and specific understanding, this position statement includes a definition and photo for two terms: "trowel pattern" and "trowel marks."




Fig. 1: Trowel pattern



Fig. 2: Trowel marks

Trowel pattern: A concrete surface feature (Fig. 1)—produced by troweling—that can be seen but can't be felt (has no vertical profile).

Trowel marks: Concrete surface features (Fig. 2)—produced by troweling—that can be seen and felt (have a vertical profile).

ASCC concrete contractors will remove trowel marks from concrete surfaces by rubbing, grinding, or other appropriate methods. A trowel pattern is not considered to be a surface defect and will not be removed from concrete floors. If trowel patterns are unacceptable, the specifier must make a specific requirement in the specification.

If you have any questions, contact your ASCC concrete contractor or the ASCC Technical Hotline at (800) 331-0668.

ASCC American Society of
Concrete Contractors

Enhancing the Capabilities of Those Who Build with Concrete

2025 S. Brentwood Blvd., Suite 105, ■ St. Louis, MO 63144
Tel: 314-962-0210 ■ Fax: 314-968-4367 ■ Toll Free: 866-788-2722
Website: www.ascconline.org ■ E-mail: ascc@ascconline.org